व. का.

## Procurement plan for next 05 year of GTE items (Diesel Locomotives) upto 2025-26 & 2026-27

| Sl. No. | PL. No. | Item Description | Unit | FY 2025-2026 | FY 2026-2027 | FY 2027-2028 | FY 2028-2029 | FY 2029-2030 |
|---|---|---|---|---|---|---|---|---|
| 1 | 16020571 | DETECTOR REPAIR INCLUDES CRANCCASE AND LOW WATER KIT | Nos. | 1052 | 808 | 723 | 861 | 861 |
| 2 | 16030618 | PISTON RING SET | Set | 13227 | 7014 | 7219 | 9153 | 9153 |
| 3 | 16040247 | REPAIR KIT FOR INJECTOR ASSEMBLY(KIT CONTAINING 11 ITEMS) | Set | 10894 | 8604 | 8243 | 9247 | 9247 |
| 4 | 16050186 | CLEVIS ASSEMBLY | Nos. | 877 | 407 | 412 | 565 | 565 |
| 5 | 16141430 | CARRIER PISTON PIN | Nos. | 8272 | 4591 | 4819 | 5894 | 5894 |
| 6 | 16150107 | RETAINER - BEARING | Nos. | 23835 | 10826 | 11113 | 15258 | 15258 |
| 7 | 16241186 | ECOTIP SUPERSTACK INJECTOR | Nos. | 4377 | 1470 | 1190 | 2346 | 2346 |
| 8 | 16241216 | VALVE ASSY. LOW WATER CUT OFF | Nos. | 923 | 420 | 432 | 592 | 592 |
| 9 | 16241228 | VALVE TEMP CONT | Nos. | 658 | 635 | 547 | 613 | 613 |
| 10 | 16241381 | BOWL BY PASS SIGHT GLASS. | Nos. | 468 | 474 | 438 | 460 | 460 |
| 11 | 16241629 | LOCK-SPRING SEAT | Nos. | 102416 | 50195 | 51905 | 68172 | 68172 |
| 12 | 16360023 | Detector ASM. As per Drg.No.9320130 | Nos. | 446 | 262 | 317 | 342 | 342 |
| 13 | 17020244 | PAD ASM - LAT THRUST | Nos. | 3441 | 2584 | 3938 | 3321 | 3321 |
| 14 | 17051228 | Pump Assembly Lube Oil Gear Driven | Nos. | 194 | 98 | 87 | 126 | 126 |
| 15 | 17270753 | STRIP- RUBBER | Mtr. | 4082 | 2106 | 1425 | 2538 | 2538 |
| 16 | 17320409 | FLEXIBLE COUPLING | Nos. | 844 | 1038 | 827 | 903 | 903 |
| 17 | 18120600 | PAD BONDED CONTACT | Nos. | 1311 | 719 | 799 | 943 | 943 |
| 18 | 19011167 | BOLT SPECIAL | Nos. | 14037 | 6346 | 6834 | 9072 | 9072 |
| 19 | 19340011 | SNAP RING | Nos. | 12578 | 6181 | 6443 | 8401 | 8401 |
| 20 | 18310072 | 800A FUSE | Nos. | 643 | 471 | 483 | 532 | 532 |
| 21 | 17273778 | SEAL DOOR | Feet | 2883 | 5339 | 6383 | 4868 | 4868 |
| 22 | 18120570 | MOTOR MODULE | Nos. | 72 | 0 | 0 | 24 | 24 |
| 23 | 18140099 | CONTACTOR -1200AMP | Nos. | 78 | 0 | 0 | 26 | 26 |
| 24 | 16130080 | Link Adjusting | Nos. | 3080 | 1140 | 1252 | 1824 | 1824 |
| 25 | 16330020 | RETAINER SEAL ASM | Nos. | 819 | 307 | 342 | 489 | 489 |
| 26 | 16060210 | Pump Assembly (Turbo Soak Back Pump) | Nos. | 431 | 185 | 201 | 272 | 272 |
| 27 | 17410095 | SPRING BRUSH HOLDER CLIP FOR CA6 | Nos. | 101 | 916 | 1106 | 708 | 708 |
| 28 | 16340139 | Plug ASM 16 PT | Nos. | 273 | 40 | 60 | 124 | 124 |
| 29 | 16241022 | SEAL OIL | Nos. | 48 | - | - | - | - |
| 30 | 16130030 | SUPPORT - ROCKER ARM | Nos. | 1184 | - | - | - | - |
| 31 | 16130339 | Crab Injector | Nos. | 448 | - | - | - | - |
| 32 | 16130340 | Bracket | Nos. | 541 | - | - | - | - |
| 33 | 16050472 | INJECTOR CONTROL SHAFT ASM- RB | Nos. | 40 | - | - | - | - |
| 34 | 16050460 | INJECTOR CONTROL SHAFT ASM- LB | Nos. | 47 | - | - | - | - |
| 35 | 16340036 | Governor for 4500 HP | Nos. | 31 | - | - | - | - |
| 36 | 16140175 | STUB SHAFT TAPER | Nos. | 25 | - | - | - | - |
| 37 | 16140990 | Support | Nos. | 24 | - | - | - | - |
| 38 | 16050174 | FUEL FILTER ASM | Nos. | 16 | - | - | - | - |
| 39 | 16140163 | STEEL- CRANKSHAFTS | Nos. | 55 | - | - | - | - |

**N.B.:** Five year requirement plan of RSP items ( child part of power pack and Crankshaft) at Sl no. 29 to 39 can not be given because Railway Board has not issued 5 year projection plan of Power pack and Crank Shaft.

अभिषेक पाण्डेय
ABHISHEK PANDEY
उप मुख्य सामग्री प्रबन्धक / आयात-II
Dy. Chief Materials Manager/Imp.-II
ब.रे.का. / वाराणसी B.L.W./Varanasi